Qty.

Item

Description			

-- 2 16.732"h aluminum Leg (lower) -- 2 16.732"h aluminum Leg (lower w/ Velcro)

-- 2 16.732"h aluminum Leg (upper) -- 2 16.732"h aluminum Leg (upper w/Velcro)

2 16.732"h aluminum Leg (upper w/Velci 1 30"w x 21.5"d Counter Base


- 1 30"w x 21.5"d Counter Shelf

1 30"w x 21.5"d Counter Top

Steps:


Note: Assemble counter upside-down.

- 1) Attach upper legs to underside of Counter Top. Twist to tighten.
- 2) Connect lower Legs through Counter Shelf to upper Legs, as shown.
- 3) Place Counter Base over lower Legs & secure with wing nuts.
- 4) Turn counter unit over & affix fabric graphic to assembly using Velcro.




When assembled

Assemble unit upside-down.








SETUP INSTRUCTIONS

General Setup Instructions


- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing

- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.



Part Identification - Numbering



Engaged Lock

Disassembly

- For loss prevention, keep all knobs & connectors attached to extrusions during disassembly.





DO NOT USE POWER TOOLS



ALL CONNECTIONS MUST BE TIGHTLY SECURED

© 2024

Top View of Each Level

